



**PRODUIT 100% COMPATIBLE  
AVEC LES FILMS HEXIS**

# ECLAT'MAX

Ce lustrant rapide simplifie l'entretien courant des surfaces filmées et renforce leur résistance à l'usure.

Il s'applique très facilement, en un temps record (+/- une demi-heure), et protège efficacement

la surface filmée contre les agressions externes et donne un effet déperlant unique.



## CONSEILS D'UTILISATION

- Agiter le flacon avant utilisation.
- Appliquer de préférence sur des surfaces propres, froides ou tièdes.
- Laver préalablement le véhicule. Essuyer très sommairement la voiture.
- Appliquer Eclat' Max sur un chiffon propre et doux, légèrement mouillé. Etaler Eclat' Max sur la surface à traiter.
- Traiter un élément à la fois (par exemple une aile).
- Essuyer avec un chiffon propre jusqu'à obtention d'un effet brillant.
- Si des taches persistent, renouveler l'essuyage avec un chiffon doux et légèrement humide.
- Traiter section par section, le reste du véhicule.

## ASTUCES

En appliquant régulièrement Eclat'Max sur vos surfaces filmées, vous renforcez la couche protectrice et garantisiez l'éclat de vos films.



**100% COMPATIBLE  
WITH HEXIS FILMS**

# ECLAT'MAX

This quick polish makes the regular maintenance of filmes surfaces easier and enhances their wear resistant.

Very easy to apply, in record time (+/-half an hour); it gives an effective protection to filmed surfaces against external damage and a unique water beading effect.



## INSTRUCTIONS FOR USE

- Shake before use.
- Apply preferably to clean, cool surfaces.
- First wash the vehicle. Give the vehicle a quick wipe.
- Apply Eclat'Max to a clean, soft and slightly moistened cloth.
- Spread the Eclat'Max over the surface.
- Treat one part at a time (e.g. a wing).
- Wipe to a shine with a soft clean cloth.
- If stains persist, repeat the wiping with a soft and damp cloth.
- Treat the rest of the vehicle section by section.

## TIPS

By giving your filmed surfaces regular applications of Eclat'Max you are strengthening the protective layer and ensuring that your filmed surfaces stays gleaming.